

# CERTIFICATE OF COMPLIANCE

**Certificate Number** E530444  
**Report Reference** E530444 - 20221014  
**Issue Date** 2022-OCTOBER-14

**Issued to:** Villareal Division Equipos S.A DE C.V  
Calle Morelos Sur 905, Colonia Centro  
Allende, Nuevo León, 67350 MX

**This certificate confirms that representative samples of** Incomplete Rotating Machines and Rotating Machine Parts - Component  
See Addendum Page for Models

Have been evaluated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

**Standard(s) for Safety:** UL 1004-1 - Rotating Electrical Machines - General Requirements  
CSA C22.2 No. 100 - Motors and Generators

**Additional Information:** See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Recognized Component Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** E530444  
**Report Reference** E530444 - 20221014  
**Issue Date** 2022-OCTOBER-14

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

**Model(s)** - MSAE6 103230, MSAE6 103460, MSAE6 153230, MSAE6 153460, MSAE6 203230  
MSAE6 203460, MSAE6 253230, MSAE6 253460, MSAE6 303230, MSAE6 303460  
MSAE6 403460, MSAE6 503460, MSAE6 53230, MSAE6 53460, MSAE6 603460, MSAE6 7.53230  
MSAE6 7.53460.



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <http://ul.com/aboutul/locations/>

